



Membrane technology have brought you benefit. But you may be facing some headaches....

- Membrane got cracked.
- Membrane got worn.
- Permeation begin turbid
- Flux became lower.
- More time for CIP cleaning.
- More maintenance.
- Running cost get higher.
- Long time waiting for spare parts.

We can help you.



SEM photo of damaged membrane layer




New gaskets



Replaced membranes



Damaged Membrane



**TANGENT**  
Your Membrane Partner

CRM ceramic membranes



Damaged membranes



Worn Membrane



Turbid Permeation



New housing



Membrane Installation



New housing on UF skid